

JUSTIFICATION FOR SOLE SOURCE (Simplified Acquisitions <\$150K)

The service or material listed on V53210 52535130 is sole source and competition is precluded for reasons indicated below. There are no substitutes available for this material or service.

Restricted to the following source. Provide original manufacturer's name. (If a sole source manufacturer distributes via dealers, ALSO provide dealer information.)

Manufacturer: Twin Disc

Manufacturer POC & phone number: Sales Department 262-638-4000

Mfr. Address: 1328 Racine St Racine, WI 53403

Dealer: Great Lakes Power Service Company

Dealer POC, phone number and address: Kenny Bauer 757-487-3670
2601 Trade St Suite E Chesapeake VA 23323

____ Description of the item or service required, the estimated cost, and required delivery date.

Anchor Winch Torque Converter rebuild, the estimated cost will be _____ and the required delivery date is 22OCT15. _____

____ Specific characteristics of the material or service that limit the availability to a sole source (unique features, function of the item, etc.). Describe in detail why only this suggested source can furnish the requirements to the exclusion of other sources.

The Anchor Winch Torque Converter needs to be rebuilt due to internal mechanical failure. Unit will be sent to Great Lakes Power Service Company for the work to be completed. They are listed as the OEM representative for Twin Disc and completed a previous rebuild of the converter in 2004 and will be able to be onsite for initial run of rebuilt unit. To achieve a satisfactory product, a factory certified repair facility is necessary. To allow the Navy to oversee the repairs, a facility within 50 miles of J.E.B. Little Creek Va is required. _____

Contracting Officer Signature

Tracey L. Doulard

Date

9-15-2015

SAP Sole Source